
Rural/Agricultural Segment: SE Green Valley Rd to SE 424th St



What are the problems?

Safety: A portion of this segment just north of SE 424th Street is part of a high accident corridor. The area around SE 400th Street is also classified as a high accident location. Collisions involving turns are the most common type of accident reported.

Safety & Traffic Backups: There is frequent truck traffic and limited opportunities to pass slower vehicles. Steep grades, slow trucks and other vehicles can create frequent traffic backups and safety hazards.











